


## AIR DIE GRINDER DIAGRAM - MODEL : SK2400



SK2400



# AIR DIE GRINDER

## MODEL : SK2400

### SPARE PARTS LIST (CHINA-CODE:601)

| No | Description    |
|----|----------------|
| 1  | Valve Screw    |
| 2  | O Ring         |
| 3  | Spring         |
| 4  | Valve Ball     |
| 5  | Valve Pin      |
| 6  | Housing        |
| 7  | Pin            |
| 8  | Lever          |
| 9  | Ball Bearing   |
| 10 | Rear Plate     |
| 11 | Steel Ball     |
| 12 | Rotor          |
| 13 | Rotor Blade    |
| 14 | Cylinder       |
| 15 | Bearing Spacer |
| 16 | Front Plate    |
| 17 | Ball Bearing   |
| 18 | Spindle        |
| 19 | Retaining Ring |
| 20 | Housing Cap    |
| 21 | Collet         |
| 22 | Collet Nut     |
| 23 | Front Plate    |
| 24 | Ball Bearing   |
| 25 | Bevel Gear     |
| 26 | Cap Lock       |
| 27 | Cap            |
| 28 | Angle Housing  |
| 29 | Ball Bearing   |
| 30 | Gear           |
| 31 | Ball Bearing   |
| 32 | Clamp Nut      |
| 33 | Spindle        |
| 34 | Collet         |
| 35 | Collet Nut     |